

VBIOS Update (2016/Oct)

1. Update BIOS to the latest 86.04.50.00.xx version
2. Improving over-clocking stability for Micron memory when using end-user OC application
3. Modifying Fan curve